KING COU. Y INTERNATIONAL AIRPORT INC. "NT REPORT

t	LIA.	INCL	IT.	Fue1	Sni	1	-
н	. 1	א-ונוו		ruei	- 201		_

DATE OCCURRED 13 July 1993

DATE REPORTED.

TIME OCCURRED 0940

TIME REPORTED

LOCATION(S) OF OCCURRENCE:

Gate 2

REPORTED BY:

PHONE NO(S):

Chief Olson

SUMMARY:

Mary, janitorial staff, called and reported fuel dripping from Bonanza N335B at gate 2.

I dispatched Off. Dickie and Mattison and also called Galvins. A bucket was placed under the dripping fuel and asorbent pads were used. $\,$ FD 2 was used later for a residual washdown.

The fuel continued to flow out the vent on the Port wing. A Galvin mechanic was contacted and he attempted further to stop fuel leak by the fuel valve and tipping the wing. A decision was made to delay defueling the plane when the leak slowed.

Attached is the pilot information. I attempted to call his residence and left a message.

Galvin said they did not fuel the plane and did not park it. A note was left by Off. Dickie for the pilot to contact us.

Mr. Frazelle brought Mr. Bicknell (an expert on Gonanzas) to the plane to help and he drained about a quart of fuel. There is a fuel leak by the Nav light and it appears it may be dangerous if the plane is started and the light turned on.

OFFICERS:

ACTION:

LEB VI 18

SHD___

G0_

— GCS ✓ JRV